

## LIST of Service Bulletins for Wartsila / Sulzer RTA type 2-stroke Diesel Engines

IT IS LIST ONLY. Links do not work. Write and Ask service Bulletins: [brovertekgr@gmail.com](mailto:brovertekgr@gmail.com)

RTA-Engines		
RTA-1	<a href="#">Recommendations Concerning Piston Running Behavior</a>	<b>01.03.1988</b> (Reprinted 02.08.1994)
RTA-01-02	<a href="#">Crosshead Bearing Vertical Bearing Clearance</a>	<b>31.01.2002</b>
RTA-2	<a href="#">Water Drain from Charge Air Receiver and Charge and Charge Air Temperature</a>	<b>05.10.1988</b> (Reprinted 09.02.1998)
RTA-3-4	<a href="#">Fuel Injection Nozzles</a>	<b>30.03.1998</b>
RTA-4	<a href="#">Oil Damping for Short Tie Rods</a>	<b>20.11.1989</b> (Reprinted 02.08.1994)
RTA-04-02	<a href="#">Crosshead Guide Shoes</a>	<b>24.04.2002</b>
RTA-5	<a href="#">Toggle Joint: Piston Cooling Oil / Crosshead Lubrication Oil Connection Linkage</a>	<b>23.05.1990</b> (Reprinted 02.08.1994)
RTA-6-2	<a href="#">Recommendations Concerning Piston Running Performance</a>	<b>29.03.1999</b>
RTA-7	<a href="#">Actuator Cam for Exhaust Valve Drive</a>	<b>27.05.1992</b>
RTA-8	<a href="#">RTA-Cylinder Liners and Reinforced Water Guide Jackets</a>	<b>15.06.1992</b> (Reprinted 18.02.1998)
RTA-9	<a href="#">Cylinder Cover with Erosion / Corrosion Resistant Cladding</a>	<b>20.07.1992</b> (Reprinted 09.02.1998)
RTA-10	<a href="#">RTA "-8 Series" Engines / Piston Skirt in two Parts</a>	<b>28.10.1992</b>
RTA-11-2	<a href="#">Fuel Injection Pump Regulating Linkage</a>	<b>11.05.2001</b>
RTA-12	<a href="#">New Piston Rod Gland Box / Undersized Piston Rods</a>	<b>11.11.1992</b>
RTA-12-2	<a href="#">Water Drain from Water Separator after Scavenge Air Cooler</a>	<b>06.12.2002</b>
RTA-13	<a href="#">Fuel Injection Nozzles 2-P Nozzle Design</a>	<b>15.06.1993</b>
RTA-14-1	<a href="#">System Oil Care and Maintenance</a>	<b>23.08.2002</b>
RTA-15	<a href="#">Elastic Studs on RTA-Type Engines</a>	<b>10.02.1994</b>
RTA-16-1	<a href="#">Retrofit for Piston Rod Stuffing Boxes / RTA "-8 Series" Engines</a>	<b>20.02.1998</b>
RTA-17-1	<a href="#">Circulation Valve to Fuel Injection Valve</a>	<b>28.02.1995</b>
RTA-18-2	<a href="#">Running-in of Cylinder Liners and Piston Rings</a>	<b>14.06.2002</b>
RTA-19	<a href="#">Oil Supply Monitoring for Geislinger Torsional Vibration Damper</a>	<b>28.10.1994</b>
RTA-20	<a href="#">Rotational Safety Studs for Roller Guide of Fuel Pump and Exhaust Valve Actuator</a>	<b>30.11.1994</b>
RTA-21	<a href="#">Improvement of Starting Behavior / all RTA equipped with DENIS-1 and DENISE-5 Engine Control System</a>	<b>10.04.1995</b>
RTA-22-1	<a href="#">Wasted Bolts for Piston Crown Spraying Plate of RTA 84C, 84M, 84T and 84CU (up-graded) Engines</a>	<b>28.11.1996</b>

RTA-23	<a href="#">Regulation of Cylinder Liner Lubrication</a>	10.07.1995
RTA-24-2	<a href="#">VTR..4 Turbochargers After Sales Service Information issued by ABB</a>	18.05.1999
RTA-25	<a href="#">Flange T 55527 for Two-Way Valve of Hydraulic Actuator Pump</a>	23.02.1996
RTA-26	<a href="#">Loss of Material on Piston Crowns due to High Temperature Corrosion and Erosion for Engines with Watercooled Pistons</a>	03.01.1996
RTA-27	<a href="#">Plastic Water Separator</a>	26.04.1996
RTA-28	<a href="#">Improvement of the Engine Control System all RTA equipped with DENIS-1 and DENISE-5 Engine Control System</a>	31.05.1996
RTA-29	<a href="#">Improved Oil Supply to the Integrated Axial Detuner equipped with Internal Oil Supply Line</a>	21.10.1996 (Reprinted 03.02.1998)
RTA-30	<a href="#">Improvement of starting behavior on RTA engines equipped with Type PGA 200 and PGA EG 200 Woodward Governor</a>	27.11.1996
RTA-31	<a href="#">Alphabetical Index of Topics of Service Bulletins</a>	23.01.1997
RTA-32	<a href="#">Alphabetical Index of Topics of Service Bulletins (RTA-38, RTA-48)</a>	24.01.1997
RTA-33	<a href="#">Crank Pin Bearing Shell</a>	11.04.1997
RTA-34	<a href="#">Fuel Injection System Modifications and Maintenance</a>	28.11.1997
RTA-35	<a href="#">Retrofit for Piston Rod Stuffing Boxes for RTA "-2 Series" Engines</a>	20.02.1998
RTA-35-1	<a href="#">Retrofit for Piston Rod Stuffing Boxes RTA „-2 and -2U Series“ Engines</a>	07.06.2001
RTA-36-1	<a href="#">Reconditioning of Piston Rods of RTA "-2 Series" Engines</a>	08.06.2001
RTA-37-1	<a href="#">Reconditioning of Piston Rods of RTA "-8 Series" Engines</a>	11.06.2001
RTA-38	<a href="#">Piston Crown Loss of Material on Combustion Side for RTA 38, 48, "-2 and -2U Series" with Oil Cooled Pistons</a>	26.02.1998
RTA-39	<a href="#">Overhaul and Reconditioning of Pistons</a>	31.03.1998
RTA-40	<a href="#">Three-step Throttle on Fuel Injection Pumps</a>	30.04.1998
RTA-41	<a href="#">Drains from Piston Underside, Piston Rod Gland Box and Air Receiver</a>	29.05.1998
RTA-42-1	<a href="#">Templates for Exhaust Valve Seat and Spindle</a>	14.03.2002
RTA-43-2	<a href="#">Piston Rings</a>	03.12.2002
RTA-44	<a href="#">Tightening Instructions for Plunger Guide Nipple</a>	26.02.1999
RTA-45	<a href="#">Tightening Instructions for Screws and Waisted Studs</a>	03.06.1999
RTA-46	<a href="#">Cracks in Column</a>	17.06.1999
RTA-47	<a href="#">Draining of Fuel Oil Pipes; Modification to Shut-off Valves of Fuel</a>	28.06.1999

	<u>Pipes and Drain Plug of Fuel Pump Block</u>	
<b>RTA-48</b>	<u>Instructions for Replacement of NOx Relevant Components on IMO Compliant Sulzer RTA Engines</u>	<b>20.09.1999</b>
<b>RTA-49</b>	<u>Gearing for Auxiliary Drives Z 42800</u>	<b>08.10.1999</b>
<b>RTA-50</b>	<u>Leakage Oil Collector in Air Spring System of Exhaust Valve</u>	<b>10.01.2000</b>
<b>RTA-51</b>	<u>Deflegation in Engine Scavenge System and Exhaust Manifold</u>	<b>21.08.2000</b>
<b>RTA-52</b>	<u>Water Separator on RTA – Type Engines</u>	<b>22.09.2000</b>
<b>RTA-53</b>	<u>Variable injection Timing and Fuel Quality Setting</u>	<b>12.06.2001</b>
<b>RTA-54</b>	<u>Electronic variable Injection Timing Troubles and Remedies</u>	<b>18.07.2001</b>
<b>RTA-55</b>	<u>Exhaust Valve Seat and Exhaust Valve Spindle</u>	<b>31.10.2001</b>
<b>RTA-56</b>	<u>Indicator Valves</u>	<b>18.07.2001</b>
<b>RTA-57</b>	<u>Improved Starting Behaviour with Quick Venting Valves</u>	<b>20.06.2002</b>
<b>RTA-58</b>	<u>Cleaning of Scavenge Air Cooler During Operation and at Standstill</u>	<b>15.10.2002</b>
<b>RTA-59</b>	<u>Procedures and Relevant Information for Sulzer RTA Engines to comply with the Annex VI NoxLimit on Testbed and on Board</u>	<b>10.02.2003</b>
<b>RTA-60-1</b>	<u>Cylinder lubrication Diagrams for Vogel PC and TA Lubricating pumps</u>	<b>09.04.2003</b>
<b>RTA-61</b>	<u>Damping elements to Piston Cooling Oil Flow Monitoring</u>	<b>25.03.2003</b>
<b>RTA-62</b>	<u>Prevention of Water Carry-Over and Liner POlishing</u>	<b>22.05.2003</b>

Last update 16.07.2003

<http://vk.od.ua/marinelibrary>